

# Product Change Notification

## PCN# 20170613100



- PCN for SolidRun's Braswell SOM which will be transitioning from:  
Revision 1.2 to Revision 1.3

Date of publication: June 13<sup>th</sup> 2017



## Table of Contents

Background .....	3
Affected SKUs .....	4
Motives.....	4
Mechanical.....	4
Electrical .....	4
Software .....	4
Contact .....	4

**Simple. Robust. Computing Solutions**

**SolidRun Ltd.**

7 Hamada st. P.O. Box 320

Yokne'am Illit 2069201

Israel

[www.solid-run.com](http://www.solid-run.com)



## Background

SolidRun will be transitioning the Braswell SOM from Revision 1.2 to Revision 1.3

### Dear customer

We are contacting all customers who - during the past twenty-four (24) months - have purchased one or more of SolidRun Ltd. products affected by this discontinuation. We would like to inquire if you will have any continuing requirements for the current revision in the future.

SOM IB8000 (SKU: SRI8000S64D04GE008V13C0) Rev 1.3

SOM IB3710 (SKU: SRI3710S64D04GE008V13C0) Rev 1.3

will be available starting June 11<sup>th</sup>, 2017 on our online store at:

<https://www.solid-run.com/product-category/braswell-soms/>

This notification period is per SolidRun Ltd. standard process.

## Affected SKUs

The impacted SKUs are all of the SKUs for Intel Braswell family. Please see an example information below on the changes of the SKUs. Different RAM/DDR configurations also apply.

EOL Product		Replacement Product	
SKU	Description	SKU	Description
SRI8000S64D04GE008V1 2C0	IB8000 64 MB SPI 4GB DDR 8GB eMMC Com . Temp R1.2	SRI8000S64D04GE008V1 3C0	IB8000 64 MB SPI 4GB DDR 8GB eMMC Com . Temp R1.3
SRI3710S64D04GE008V1 2C0	IB3710 64 MB SPI 4GB DDR 8GB eMMC Com . Temp R1.2	SRI3710S64D04GE008V1 3C0	IB3710 64 MB SPI 4GB DDR 8GB eMMC Com . Temp R1.3

## Motives

The motives for this product revision are minor bug fixes and improvements.

## Mechanical

No mechanical changes have been made to the Braswell SOM.

## Electrical

Minor electrical change, SolidRun has added capacitor C440. Revisions 1.1 & 1.2 did not have this capacitor; capacitance on this rail was lacking which could cause CRC errors on the ethernet interface.

## Software

No software changes have been made to the Braswell SOM.

## Contact

Please contact SolidRun if you have any questions.

For commercial and sales inquiries please email: [sales@solid-run.com](mailto:sales@solid-run.com)

For technical questions please email: [support@solid-run.com](mailto:support@solid-run.com)